

# SERVICE BULLETIN



No. : 0IVL20060069

Date : 2006-08-02

Model	Factory	Factory Model	Suffix	Model No.	Factory	Factory Model	Suffix	Model No.
	EKHQ	32LX2R-TE	AMALLH	32LX2R	EKHQ	32LX2R-TE	ATRLH	32LX2R
Buyer	Buyer Name	Buyer Code	Buyer Name	Buyer Code	Buyer Name	Buyer Code		
	LGEUS	US000001	LGEAI	US000002				
EFFECTIVE DATE	2006-08-02		EFFECTIVE FROM(SERIAL NO.)				All of range	
Subject	Solution of latch problem for ML-051A							
No.	Loc No.	Before Change		After Change		Note	K-Code	Remark
		Part No	DESC./SPEC.	Part No	DESC./SPEC.			
Reason Of Change								
Version Check Instructions pdf Micom related. rar								

\*\* FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

NOTE(**) : INTERCHANGEABILITY CODE				KEY-WORD CODE
	Parts	Set		
A	Original	Early		1. To improve performance 2. To improve productivity
	New	Late		
B	Original	Early		3. To improve reliability 4. Change of material or dimension
	New	Late		
C	Original	Early		5. Addition 6. Deletion
	New	Late		
D	Original	Early		7. Correction
	New	Late		

CHIEF ENGINEER , *approved*  
Factory.